WATER SYSTEM FIVE YEAR PERMIT REVIEW

Water System Name: PG&E OAKHURST SERVICE CENTER

LEA ID: 2000733

SUMMARIZED BELOW IS A LIST OF ACTIVE SOURCES

PRIMARY STATION CODE	SITE DESCRIPTION
2000733-001	Source Old Well-Emergency-destroyed 2008
2000733-002	Source Main Well

Area Served

This system is permitted as a Non-Transient Non-Community Water System that serves the Oakhurst PG&E maintenance yard and the service center for Oakhurst PG&E customers. The system has 30 full time employees at this site with up to 50 employees brought in from other areas to help with power outages and special construction projects. It is located in the hills of eastern Madera County at approximately 3,000 feet elevation. The area around the site is mainly developed for residential uses with some commercial or industrial development.

Does the description need to be changed Y/N N ?

If YES please enter description changes below. Attach additional pages if needed.

Sources

The PG&E Oakhurst Service Center consists of a single potable ground water well source, Well #2 #2000733-002, is located 500 feet north of the office adjacent to Road 426. The well contains a submersible pump which is controlled from a float switch that is located on the 1550 gallon storage tank. The "Old Well" source # 2000733-001 was destroyed on 11/05/2008 and deleted from the water system source inventory. Well #2 was drilled in 1988 by Walt Bannon Drilling Co., Inc., has a 6 5/8" diameter steel casing installed from 0 to 50 feet and is 625 drilled well depth. The completed well depth and annular seal depth is unknown. It has a 5 HP submersible pump and produces 8 gallons per minute. The well construction contains 1 1/4 " a galvanized steel discharge pipe, a source water sample tap, check valve and totalizer flow meter, mounted at the inlet of the storage tank.

Does the description need to be changed Y/N Y ?

If YES please enter description changes below. Attach additional pages if needed.

We do not have the drill well Log.

WATER SYSTEM FIVE YEAR PERMIT REVIEW

Survey

The main sanitary hazards for the site are the underground fuel tanks and the onsite septic system. The fuel tanks are new double wall containment with modern leak detection. The well in use is 500 feet from the tanks and is not considered a problem. The septic system is also aboout 500 feet from the well and is in good working condition.

Does the description need to be changed Y/N Y ?

If YES please enter description changes below. Attach additional pages if needed.

UNDER Ground Fuel tanks Have Been Removed. & the septic tank is over 700 feet from well.

Appraisal

System has had history of Total Coliform positive results and is part of the reason that a continuous feed chlorinator was installed. Raw water monitoring of the well has been on-going and indicates the presence of coliform at the source.

Does the description need to be changed Y/N Y ?

If YES please enter description changes below. Attach additional pages if needed.

We have had series of Coliform results and am continue to try and determine where the coliform is present.

Cross Connect

Behind the fire tank there is a cross connection device.

Does the description need to be changed Y/N N ?

If YES please enter description changes below. Attach additional pages if needed.

WATER SYSTEM FIVE YEAR PERMIT REVIEW

Storage/Dist.

Well #2 fills a 1,550 gallon atmospheric storage tank to provide water during high water usage periods to compensate for the low well production. A vent is located on the man-hole access cover to prevent negative pressure inside the tank. The vent is down-turned and screened. The tank contains a drain to waste valve near the bottom of the tank. This drain valve allows for periodic flushing to help remove sediment which may settle at the bottom of the tank. The discharge line for the storage tank feeds the booster pump to maintain pressure in the system. The pressure tank for the facility consists of a single 85 gallon bladder tank. The pressure tank provides storage capacity for the pressurized section of the water distribution system. A fire protection storage tank is located on the property and is only used for emergencies. The fire protection tank is filled by the potable water distribution system and is protected by a back flow prevention device installed at the the inlet of the fire protection tank. The water and pressure for the distribution system is provided by a booster pump installed at the outlet of the storage tank. The booster pump is controlled by a pressure switch that is installed near the 85 gallon bladder tank. The distribution system supplies water to restrooms, sinks, and outside hose bibs.

Does the description need to be changed Y/N N ?

If YES please enter description changes below. Attach additional pages if needed.

Treatment

Currently an interim chlorination system is being used to provide a disinfectant residual, as a preventative measure, to all points of potable water usage. Chlorine residual is tested at the same time that the monthly bacteriological sample is obtained. The proposed permanent chemical injection pump is manufactured by Walchem and is NSF 61 approved. The proposed permanent chemical solution tank for the interim chlorination system is manufactured by Snyder Industries, Inc. This model tank is currently being used for the ICS and is NSF 61 approved. The permanent chlorination building is manufactured by Rubber Maid and will house the chlorination injection equipment and chlorine tank to restrict sunlight exposure to prevent degrading the chlorine solution. An eye wash station, Porta-Stream II or equivalent is installed inside of the chlorination building and a chlorination spill kit that could handle a 65 gallon spill will be kept inside the chlorination building. The proposed chlorine analyzer Rosemount or equivalent will be installed and used to monitor the free chlorine residual. Minimum and maximum chlorine residual set points programmed into the analyzer will trip an alarm relay to activate a strobe light and audible alarm that will be installed on the outside of the analyzer room on the main building. A sign will be installed by the alarm that will inform the person responding to the alarm to call the EFS representative and the CSO. The water supply to this unit will be taken from the piping near the pressure tank. A 12.5 % NSF Sodium Hypo chlorite will be placed in the solution tank and there will be a 9 gallons water to 1 gallon sodium hypochlorite ratio. The chemical injection pump will be energized in conjuction when the deep well is running. The pump will then draft the chlorine solution out of the solution tank and inject into the inlet piping prior to entering the atmospheric storage tank. The 1550 gallon atmospheric storage tank will provide mixing of the injected chlorine solution and domestic water, prior to being discharged out to the distribution sytem. The water will flow continuously through the chlorine analyzer which in turn will provide a free chlorine residual reading.

Does the description need to be changed Y/N Y ?

If YES please enter description changes below. Attach additional pages if needed.

NO Cl_2 ANALYZER IS ON SITE

NO ALARM FOR Cl_2 ON SITE.

Consumer Confidence Report
Certification Form

Water System Name: **PG&E OAKHURST SERVICE CENTER**
Water System Number: **2000733**

The water system named above hereby certifies that its Consumer Confidence Report was distributed on 5/30/2012 (date) to customers (and appropriate notices of availability have been given). Further, the system certifies that the information contained in the report is correct and consistent with the compliance monitoring data previously submitted to the Department of Public Health.

Certified By: Name Wayne Pacheco

Signature Wayne Pacheco

Title SENIOR ENVIRONMENTAL FIELD SPECIALIST

Phone Number (209) 212-1364 Date 5/30/2012

==========

To summarize report delivery used and good-faith efforts taken, please complete the below by checking all items that apply and fill-in where appropriate:

✓ CCR was distributed by mail or other direct delivery methods. Specify other direct delivery method used: Posted AT OAKHURST SERVICE Center in hallway.

✓ "Good faith" efforts were used to reach non-bill paying customers. Those efforts included the following methods:

__ Posted the CCR on the internet at www._____

__ Mailed the CCR to postal patrons within the service area (attach zip codes used)

__ Advertised the availability of the CCR in news media (attach copy of press release)

__ Publication of the CCR in a local newspaper of general circulation (attach a copy of the published notice, including name of the newspaper and date published)

✓ Posted the CCR in public places (attach a list of locations)

__ Delivery of multiple copies of CCR to single bill addresses serving several persons, such as apartments, businesses and schools

__ Delivery to community organizations (attach a list of organizations)

__ For systems serving at least 100,000 persons: Posted CCR on a publicly-accessible internet site at the following address: www._____

__ For privately-owned utilities: Delivered the CCR to the California Public Utilities Commission

(Submit this form and a copy of your CCR to the Department of health Services)

2011 Consumer Confidence Report

Water System Name: **PG&E OAKHURST SERVICE CENTER** Report Date: March 2012

We test the drinking water quality for many constituents as required by state and federal regulations. This report shows the results of our monitoring for the period of January 1 - December 31, 2011

Este informe contiene información muy importante sobre su agua beber. Tradúzcalo ó hable con alguien que lo entienda bien.

Type of water sources(s) in use: This info is not available, as this water system does not have a completed assessment on file. Please see the Drinking Water Source Assessment Information section located at the end of this report for more details.

Your water comes from 1 source: Well.

For more information about this report, or for any questions relating to your drinking water, please call (209) 838 - 7842 and ask for Quality Service, Inc..

TERMS USED IN THIS REPORT:

Maximum Contaminant Level (MCL): The highest level of a contaminant that is allowed in drinking water. Primary MCLs are set as close to the PHGs (or MCLGs) as is economically and technologically feasible. Secondary MCLs are set to protect the odor, taste, and appearance of drinking water.

Maximum Contaminant Level Goal (MCLG): The level of a contaminant in drinking water below which there is no known or expected risk to health. MCLGs are set by the U.S. Environmental Protection Agency.

Public Health Goal (PHG): The level of a contaminant in drinking water below which there is no known or expected risk to health. PHGs are set by the California Environmental Protection Agency.

Maximum Residual Disinfectant Level (MRDL): The highest level of a disinfectant allowed in drinking water. There is convincing evidence that addition of a disinfectant is necessary for control of microbial contaminants.

Maximum Residual Disinfectant Level Goal (MRDLG): The level of a drinking water disinfectant below which there is no known or expected risk to health. MRDLGs do not reflect the benefits of the use of disinfectants to control microbial contaminants.

Primary Drinking Water Standards (PDWS): MCLs for contaminants that affect health along with their monitoring and reporting requirements, and water treatment requirements.

Secondary Drinking Water Standards (SDWS): MCLs for contaminants that affect taste, order, or appearance of the drinking water. Contaminants with SDWSs do not affect the health at the MCL levels.

Treatment Technique (TT): A required process intended to reduce the level of a contaminant in drinking water.

Regulatory Action Level (AL): The concentration of a contaminant which, if exceeded, triggers treatment or other requirements which a water system must follow.

Variances and Exemptions: Department permission to exceed an MCL or not comply with a treatment technique under certain conditions.

ND: not detectable at testing limit
ppm: parts per million or milligrams per liter (mg/L)
ppb: parts per billion or micrograms per liter (µg/L)
ppt: parts per trillion or nanograms per liter (ng/L)
ppq: parts per quadrillion or picograms per liter (pg/L)
pCi/l: picocuries per liter (a measure of radioactivity)

The sources of drinking water(both tap water and bottled water) include rivers, lakes, streams, ponds, reservoirs, spring, and wells. As water travels over the surface of the land or through the ground, it dissolves naturally-occurring minerals and, in some cases, radioactive material, and can pick up substances resulting from the presence of animals or from human activity.

2011 Consumer Confidence Report

Contaminants that may be present in source water include:

- *Microbial contaminants,* such as viruses and bacteria, which may come from sewage treatment plants, septic systems, agricultural livestock operations and wildlife.
- *Inorganic contaminants,* such as salts and metals, which can be naturally-occurring or result from urban stormwater runoff, industrial or domestic wastewater discharges, oil and gas production, mining or farming.
- *Pesticides and herbicides,* which may come from a variety of sources such as agriculture, urban stormwater runoff, and residential uses.
- *Radioactive contaminants,* which can be naturally occurring or the result of oil production and mining activities.
- *Organic chemical contaminants,* including synthetic and volatile organic chemicals, which are byproducts of industrial processes and petroleum production, and can also come from gas stations, urban stormwater runoff, and septic systems.

In order to ensure that tap water is safe to drink, the U.S. Environmental Protection Agency (USEPA) and the California Department of Health Services (Department) prescribes regulations which limit the amount of certain contaminants in water provided by public water systems. Department regulations also establish limits for contaminants in bottled water that must provide the same protection for public health.

Tables 1,2,3,4,5 and 6 list all of the drinking water contaminants that were detected during the most recent sampling for the constituents. The presence of these contaminants in the water does not necessarily indicate that the water poses a health risk. The Department allows us to monitor for certain contaminants less than once per year because the concentrations of these contaminants do not change frequently. Some of the data, though representative of the water quality, are more than one year old.

TABLE 1 - SAMPLING RESULTS SHOWING THE DETECTION OF COLIFORM BACTERIA

Microbiological Contaminants (complete if bacteria detected)	Highest No.of Detections	No. of Months in Violation	MCL	MCLG	Typical Sources of Contaminant
Total Coliform Bacteria	1/mo. (2011)	0	no more than 1 positive monthly sample	0	Naturally present in the environment.

TABLE 2 - SAMPLING RESULTS SHOWING THE DETECTION OF LEAD AND COPPER

Lead and Copper (complete if lead or copper detected in the last sample set)	No. of Samples Collected	90th Percentile Level	No. Site Exceeding AL	AL	PHG	Typical Sources of Contaminant
Lead (Pb) (ppb)	5 (2010)	6.75	0	15	0.2	Internal corrosion of household water plumbing systems; discharges from industrial manufacturers, erosion of natural deposits
Copper (ppm)	5 (2010)	0.797	0	1.3	.17	Internal corrosion of household plumbing systems; erosion of natural deposits; leaching from wood preservatives

2011 Consumer Confidence Report

TABLE 3 - SAMPLING RESULTS FOR SODIUM AND HARDNESS						
Chemical or Constituent (and reporting units)	Sample Date	Level Detected	Range of Detections	MCL (MRDL)	PHG (MCLG)	Typical Sources of Contaminant
Sodium (ppm)	2008	13	13 - 13	none	none	Salt present in the water and is generally naturally occurring
Hardness (ppm)	2008	91	91 - 91	none	none	Sum of polyvalent cations present in the water, generally magnesium and calcium, and are usually naturally occurring

TABLE 4 - DETECTION OF CONTAMINANTS WITH A PRIMARY DRINKING WATER STANDARD						
Chemical or Constituent (and reporting units)	Sample Date	Level Detected	Range of Detections	MCL (MRDL)	PHG (MCLG) [MRDLG]	Typical Sources of Contaminant
Barium (Ba) ppm	2011	0.007	0.007 - 0.007	1	2	Discharge from oil drilling wastes and from metal refineries; erosion of natural deposits
Nitrate (NO3) ppm	2011	16.7	17 - 17	45	45	Runoff and leaching from fertilizer use; leaching from septic tanks and sewage; erosion of natural deposits
Gross Alpha pCi/L	2009	12.4	12 - 13	15	n/a	Erosion of natural deposits.
Uranium pCi/L	2009	16	13 - 19	20	0.5	Erosion of natural deposits

TABLE 5 - DETECTION OF CONTAMINANTS WITH A SECONDARY DRINKING WATER STANDARD						
Chemical or Constituent (and reporting units)	Sample Date	Level Detected	Range of Detections	MCL (MRDL)	PHG (MCLG)	Typical Sources of Contaminant
Chloride ppm	2008	8	8 - 8	500	n/a	Runoff/leaching from natural deposits; seawater influence
Corrosivity (Langlier Index)	2008	-0.9	-0.9 - -0.9	> 0	n/a	Natural or industrial-influenced balance of hydrogen, carbon and oxygen in the water, affected by temperature and other factors.
Iron (Fe) ppb	2008	70	70 - 70	300	n/a	Leaching from natural deposits; Industrial wastes
Specific Conductance umhos/cm	2008	259	259 - 259	1600	n/a	Substances that form ions when in water; seawater influence
Sulfate (SO4) ppm	2008	7.00	7.0 - 7.0	500	n/a	Runoff/leaching from natural deposits; industrial wastes
TDS ppm	2008	160	160 - 160	1000	n/a	Runoff/leaching from natural deposits
Zinc (Zn) ppm	2008	0.09	0.09 - 0.09	5	n/a	Runoff/leaching from natural deposits

Any violation of MCL,AL or MRDL is shaded. Additional information regarding the violation is provided later in this report.

TABLE 6 - DETECTION OF UNREGULATED CONTAMINANTS					
Chemical or Constituent (and reporting units)	**Sample Date**	**Level Detected**	**Range of Detections**	**Notification Level**	**Health Effects Language**
Boron ppm	2008	0.1	0.1 - 0.1 (2008)	1	The babies of some pregnant women who drink water containing boron in excess of the notification level may have an increased risk of developmental effects, based on studies in laboratory animals.
Vanadium ppm	2011	0.005	0.005 - 0.005 (2011)	0.05	The babies of some pregnant women who drink water containing vanadium in excess of the action level may have an increased risk of developmental effects, based on studies in laboratory animals.

Additional General Information on Drinking Water

Drinking water, including bottled water, may reasonably be expected to contain at least small amounts of some contaminants. The presence of contaminants does not necessarily indicate that water poses a health risk. More information about contaminants and potential health effects can be obtained by calling the USEPA's Safe Drinking Water Hotline (800-426-4791).

Some people may be more vulnerable to contaminants in drinking water than the general population. Immuno-compromised persons such as persons with cancer undergoing chemotherapy, persons who have undergone organ transplants, people with HIV/AIDS or other immune system disorders, some elderly, and infants can be particularly at risk from infections. These people should seek advice about drinking water from their health care provider. USEPA/Centers for Disease Control (CDC) guidelines on appropriate means to lessen the risk of infection by *Cryptosporidium* and other microbial contaminants are available from the Safe Drinking Water Hotline (800-426-4791)

For Lead (Pb), If present, elevated levels of lead can cause serious health problems, especially for pregnant women and young children. Lead in drinking water is primarily from materials and components associated with service lines and home plumbing. *PG&E OAKHURST SERVICE CENTER* is responsible for providing high quality drinking water, but cannot control the variety of materials used in plumbing components. When your water has been sitting for several hours, you can minimize the potential for lead exposure by flushing your tap for 30 seconds to 2 minutes before using water for drinking or cooking. If you are concerned about lead in your water, you may wish to have your water tested. Information on lead in drinking water, testing methods, and steps you can take to minimize exposure is available from the Safe Drinking Water Hotline or at http://www.epa.gov/safewater/lead.

Summary Information for Contaminants Exceeding an MCL, MRDL, or AL, or a violation of Any Treatment Technique or Monitoring and Reporting Requirement

About our Corrosivity (Langlier Index): Corrosivity less than 0 indicates your water may be corrosive to the plumbing and fixtures. The Corrosivity MCL was set to protect you against unpleasant aesthetic affects such as color, taste and odor. Violating this MCL does not pose a risk to public health.

Drinking Water Source Assessment Information

Assessment Info

According to the Drinking Water Source Assessment and Protection Program's Source Water Assessments Public Access web page, the Public Water Sources WELL of the PG&E OAKHURST SERVICE CENTER water system number 2000733, does not have a completed Source Water Assessment on file.

Discussion of Vulnerability

Assessment summaries are not available for some sources. This is because:

- The Assessment has not been completed. Contact the local Department of Health Services (DHS) Drinking Water field office or the water system to find out when the Assessment is scheduled to be done.
- The source is not active. It may be out of service, or new and not yet in service.
- The Assessment was not submitted electronically. The site used to obtain Assessments only provides access to Assessment summaries submitted electronically.

Acquiring Info

For more info you may visit http://swap.ice.ucdavis.edu/TSinfo/TSintro.asp or contact the health department in the county to which the water system belongs.

PG&E OAKHURST SERVICE CENTER
Analytical Results By FGL - 2011

MICROBIOLOGICAL CONTAMINANTS									
		Units	MCLG	CA-MCL	PHG	Sampled	Result	Avg. Result(a)	Range (b)
Total Coliform Bacteria			0	5%				12.5 %	0 - 1
Kit. Sink	STK1150977-001					12/14/2011	<1.0		
FLEET GRGE	STK1150977-002					12/14/2011	<1.0		
STRGE TANK	STK1150977-003					12/14/2011	<1.0		
WELL	STK1150977-004					12/14/2011	<1.0		
Kit. Sink	STK1150193-001					11/16/2011	<1.0		
FLEET GRGE	STK1150193-002					11/16/2011	<1.0		
STRGE TANK	STK1150193-003					11/16/2011	<1.0		
WELL	STK1150193-004					11/16/2011	<1.0		
WELL	STK1139156-001					10/13/2011	<1.0		
Kit. Sink	STK1139156-002					10/13/2011	<1.0		
STRGE TANK	STK1139156-003					10/13/2011	<1.0		
FLEET GRGE	STK1139156-004					10/13/2011	<1.0		
Kit. Sink	STK1139091-001					10/12/2011	>200.5		
FLEET GRGE	STK1139091-002					10/12/2011	<1.0		
STRGE TANK	STK1139091-003					10/12/2011	<1.0		
WELL	STK1139091-004					10/12/2011	<1.0		
Kit. Sink	STK1138101-001					09/14/2011	<1.0		
FLEET GRGE	STK1138101-002					09/14/2011	<1.0		
STRGE TANK	STK1138101-003					09/14/2011	<1.0		
WELL	STK1138101-004					09/14/2011	<1.0		
Kit. Sink	STK1137097-001					08/10/2011	<1.0		
FLEET GRGE	STK1137097-002					08/10/2011	<1.0		
STRGE TANK	STK1137097-003					08/10/2011	<1.0		
WELL	STK1137097-004					08/10/2011	<1.0		
Kit. Sink	STK1136090-001					07/13/2011	<1.0		
FLEET GRGE	STK1136090-002					07/13/2011	<1.0		
STRGE TANK	STK1136090-003					07/13/2011	<1.0		
WELL	STK1136090-004					07/13/2011	<1.0		
Kit. Sink	STK1134888-001					06/08/2011	<1.0		
FLEET GRGE	STK1134888-002					06/08/2011	<1.0		
STRGE TANK	STK1134888-003					06/08/2011	<1.0		
WELL	STK1134888-004					06/08/2011	<1.0		
Kit. Sink	STK1133984-001					05/11/2011	<1.0		
FLEET GRGE	STK1133984-002					05/11/2011	<1.0		
STRGE TANK	STK1133984-003					05/11/2011	<1.0		
WELL	STK1133984-004					05/11/2011	<1.0		
Kit. Sink	STK1133258-001					04/18/2011	<1.0		
FLEET GRGE	STK1133258-002					04/18/2011	<1.0		
STRGE TANK	STK1133258-003					04/18/2011	<1.0		
WELL	STK1133258-004					04/18/2011	<1.0		
WELL	STK1133124-001					04/13/2011	<1.0		
STRGE TANK	STK1133124-002					04/13/2011	<1.0		
Kit. Sink	STK1133124-003					04/13/2011	<1.0		
FLEET GRGE	STK1133124-004					04/13/2011	<1.0		
WELL	STK1132717-001					04/03/2011	<1.0		
Strge Tank	STK1132717-002					04/03/2011	<1.0		
Kit. Sink	STK1132717-003					04/03/2011	<1.0		
FLEET GARAGE	STK1132717-004					04/03/2011	<1.0		
Kit. Sink	STK1132061-001					03/09/2011	<1.0		
FLEET GRGE	STK1132061-002					03/09/2011	<1.0		
STRGE TANK	STK1132061-003					03/09/2011	<1.0		
WELL	STK1132061-004					03/09/2011	<1.0		
Kit. Sink	STK1131275-001					02/09/2011	<1.0		
FLEET GRGE	STK1131275-002					02/09/2011	<1.0		
STRGE TANK	STK1131275-003					02/09/2011	<1.0		
WELL	STK1131275-004					02/09/2011	<1.0		
Kit. Sink	STK1130442-001					01/12/2011	<1.0		
FLEET GRGE	STK1130442-002					01/12/2011	<1.0		
STRGE TANK	STK1130442-003					01/12/2011	<1.0		
WELL	STK1130442-004					01/12/2011	<1.0		

PG&E OAKHURST SERVICE CENTER
Analytical Results By FGL - 2011

LEAD AND COPPER RULE									
		Units	MCLG	CA-MCL	PHG	Sampled	Result	90th Percentile	# Samples
Lead (Pb)		ppb	0	15	0.2			6.75	5
Lead (Pb)									
WELL	STK1151008-001	ppb				12/15/2011	0.00		
Copper		ppm		1.3	.17			0.797	5
Kitchen Sink	STK1036389-001	ppm				07/14/2010	0.418		
Girls Bathroom	STK1036389-002	ppm				07/14/2010	0.769		
Boys Bathroom R	STK1036389-003	ppm				07/14/2010	0.374		
Boys Bathroom L	STK1036389-004	ppm				07/14/2010	0.825		
Outside by Ice	STK1036389-005	ppm				07/14/2010	0.145		

SAMPLING RESULTS FOR SODIUM AND HARDNESS									
		Units	MCLG	CA-MCL	PHG	Sampled	Result	Avg. Result(a)	Range (b)
Sodium		ppm		none	none			13	13 - 13
Domestic We;;	VI 0841957-007	ppm				08/29/2008	13.0		
Hardness		ppm		none	none			91	91 - 91
Domestic We;;	VI 0841957-007	ppm				08/29/2008	91.2		

PRIMARY DRINKING WATER STANDARDS (PDWS)									
		Units	MCLG	CA-MCL	PHG	Sampled	Result	Avg. Result(a)	Range (b)
Barium (Ba)		ppm	2	1	2			0.007	0.007 - 0.007
WELL	STK1151008-001	ppm				12/15/2011	0.00680		
Nitrate (NO3)		ppm		45	45			16.7	17 - 17
WELL	STK1151008-001	ppm				12/15/2011	16.7		
Gross Alpha		pCi/L		15				12.4	12 - 13
Domestic Water	VI 0940915-002	pCi/L				05/04/2009	11.9		
Domestic Water	VI 0940244-007	pCi/L				02/09/2009	13.0		
Uranium		pCi/L		20	0.5			16	13 - 19
Domestic Water	VI 0940915-002	pCi/L				05/04/2009	13.2		
Domestic Water	VI 0940244-007	pCi/L				02/09/2009	18.8		

SECONDARY DRINKING WATER STANDARDS (SDWS)									
		Units	MCLG	CA-MCL	PHG	Sampled	Result	Avg. Result(a)	Range (b)
Chloride		ppm		500				8	8 - 8
Domestic We;;	VI 0841957-007	ppm				08/29/2008	8.00		
Corrosivity (Langlier Index)				> 0				-0.9	-0.9 - -0.9
Domestic We;;	VI 0841957-007					08/29/2008	-0.9		
Iron (Fe)		ppb		300				70	70 - 70
Domestic We;;	VI 0841957-007	ppb				08/29/2008	70.0		
Specific Conductance		umhos/cm		1600				259	259 - 259
Domestic We;;	VI 0841957-007	umhos/cm				08/29/2008	259		
Sulfate (SO4)		ppm		500				7.00	7.0 - 7.0
Domestic We;;	VI 0841957-007	ppm				08/29/2008	7.00		
TDS		ppm		1000				160	160 - 160
Domestic We;;	VI 0841957-007	ppm				08/29/2008	160		
Zinc (Zn)		ppm		5				0.09	0.09 - 0.09
Domestic We;;	VI 0841957-007	ppm				08/29/2008	0.0900		

UNREGULATED CONTAMINANTS									
		Units	MCLG	CA-MCL	PHG	Sampled	Result	Avg. Result(a)	Range (b)
Boron		ppm		NS				0.1	0.1 - 0.1
Domestic We;;	VI 0841957-007	ppm				08/29/2008	0.100		
Vanadium		ppm		NS				0.005	0.005 - 0.005

PG&E OAKHURST SERVICE CENTER
Analytical Results By FGL - 2011

UNREGULATED CONTAMINANTS									
		Units	MCLG	CA-MCL	PHG	Sampled	Result	Avg. Result(a)	Range (b)
Vanadium									
WELL	STK1151008-001	ppm				12/15/2011	0.00500		

PG&E OAKHURST SERVICE CENTER
CCR Login Linkage - 2011

FGL CODE	DATE SAMPLED	LAB ID	METHOD	DESCRIPTION	PROPERTY
Boys Bathroom L	07/14/2010	STK1036389-004	Metals, Total	Boys Bathroom L	Lead & Copper Monitoring
Boys Bathroom R	07/14/2010	STK1036389-003	Metals, Total	Boys Bathroom R	Lead & Copper Monitoring
Breakroom	08/29/2008	VI 0841957-002	Metals, Total	Breakroom	Bacteria Monitoring
	02/09/2009	VI 0940244-002	Metals, Total	Breakroom	Bacteria Monitoring
Domestic Water	10/16/2008	VI 0842424-002	Radio Chemistry	Domestic Water	Bacteria Monitoring
	02/09/2009	VI 0940244-007	EPA 524.2	Domestic Water	Bacteria Monitoring
	02/09/2009	VI 0940244-007	Radio Chemistry	Domestic Water	Bacteria Monitoring
	02/09/2009	VI 0940244-007	Wet Chemistry	Domestic Water	Bacteria Monitoring
	05/04/2009	VI 0940915-002	Radio Chemistry	Domestic Water System Main Wel	Bacteria Monitoring
	05/04/2009	VI 0940915-002	Wet Chemistry	Domestic Water System Main Wel	Bacteria Monitoring
Domestic We;;	08/29/2008	VI 0841957-007	EPA 507	Domestic Well	Bacteria Monitoring
	08/29/2008	VI 0841957-007	EPA 524.2	Domestic Well	Bacteria Monitoring
	08/29/2008	VI 0841957-007	General Mineral	Domestic Well	Bacteria Monitoring
	08/29/2008	VI 0841957-007	Metals, Total	Domestic Well	Bacteria Monitoring
	08/29/2008	VI 0841957-007	Radio Chemistry	Domestic Well	Bacteria Monitoring
	08/29/2008	VI 0841957-007	Wet Chemistry	Domestic Well	Bacteria Monitoring
FLEET GARAGE	04/03/2011	STK1132717-004	Coliform	Fleet Garage	Water Monitoring
FLEET GRGE	01/12/2011	STK1130442-002	Coliform	Fleet Garage	Drinking Water Monitoring
	02/09/2011	STK1131275-002	Coliform	Fleet Garage	Drinking Water Monitoring
	03/09/2011	STK1132061-002	Coliform	Fleet Garage	Drinking Water Monitoring
	04/13/2011	STK1133124-004	Coliform	Fleet Garage	Water Monitoring
	04/18/2011	STK1133258-002	Coliform	Fleet Garage	Drinking Water Monitoring
	05/11/2011	STK1133984-002	Coliform	Fleet Garage	Drinking Water Monitoring
	06/08/2011	STK1134888-002	Coliform	Fleet Garage	Drinking Water Monitoring
	07/13/2011	STK1136090-002	Coliform	Fleet Garage	Drinking Water Monitoring
	08/10/2011	STK1137097-002	Coliform	Fleet Garage	Drinking Water Monitoring
	09/14/2011	STK1138101-002	Coliform	Fleet Garage	Drinking Water Monitoring
	10/12/2011	STK1139091-002	Coliform	Fleet Garage	Drinking Water Monitoring
	10/13/2011	STK1139156-004	Coliform	Fleet Garage	Drinking Water Monitoring
	11/16/2011	STK1150193-002	Coliform	Fleet Garage	Drinking Water Monitoring
	12/14/2011	STK1150977-002	Coliform	Fleet Garage	Drinking Water Monitoring
Girls Bathroom	07/14/2010	STK1036389-002	Metals, Total	Girls Bathroom	Lead & Copper Monitoring
Hall Fountain	02/09/2009	VI 0940244-004	Metals, Total	Hall Fountain	Bacteria Monitoring
HB E/S of Main	09/27/2010	STK1037634-001	EPA 551.1	HB E/S of Main Office	TTHM & HAA5 Monitoring
	09/27/2010	STK1037634-001	EPA 552.2	HB E/S of Main Office	TTHM & HAA5 Monitoring
Kit. Sink	01/12/2011	STK1130442-001	Coliform	Kitchen Sink	Drinking Water Monitoring
	02/09/2011	STK1131275-001	Coliform	Kitchen Sink	Drinking Water Monitoring
	03/09/2011	STK1132061-001	Coliform	Kitchen Sink	Drinking Water Monitoring
	04/03/2011	STK1132717-003	Coliform	Kitchen Sink	Water Monitoring
	04/13/2011	STK1133124-003	Coliform	Kitchen Sink	Water Monitoring
	04/18/2011	STK1133258-001	Coliform	Kitchen Sink	Drinking Water Monitoring
	05/11/2011	STK1133984-001	Coliform	Kitchen Sink	Drinking Water Monitoring
	06/08/2011	STK1134888-001	Coliform	Kitchen Sink	Drinking Water Monitoring
	07/13/2011	STK1136090-001	Coliform	Kitchen Sink	Drinking Water Monitoring
	08/10/2011	STK1137097-001	Coliform	Kitchen Sink	Drinking Water Monitoring
	09/14/2011	STK1138101-001	Coliform	Kitchen Sink	Drinking Water Monitoring
	10/12/2011	STK1139091-001	Coliform	Kitchen Sink	Drinking Water Monitoring
	10/13/2011	STK1139156-002	Coliform	Kitchen Sink	Drinking Water Monitoring
	11/16/2011	STK1150193-001	Coliform	Kitchen Sink	Drinking Water Monitoring
	12/14/2011	STK1150977-001	Coliform	Kitchen Sink	Drinking Water Monitoring
Kitchen Sink	07/14/2010	STK1036389-001	Metals, Total	Kitchen Sink	Lead & Copper Monitoring
Mens Restroom	02/09/2009	VI 0940244-003	Metals, Total	Mens Restroom	Bacteria Monitoring
N/W Faucet (Off	02/09/2009	VI 0940244-005	Metals, Total	N/W Faucet (Office)	Bacteria Monitoring
Outside by Ice	07/14/2010	STK1036389-005	Metals, Total	Outside by Ice machine hook-up	Lead & Copper Monitoring
Shop Faucet	02/09/2009	VI 0940244-006	Metals, Total	Shop Faucet	Bacteria Monitoring
STRGE TANK	01/12/2011	STK1130442-003	Coliform	Storage Tank	Drinking Water Monitoring
	02/09/2011	STK1131275-003	Coliform	Storage Tank	Drinking Water Monitoring
	03/09/2011	STK1132061-003	Coliform	Storage Tank	Drinking Water Monitoring
Strge Tank	04/03/2011	STK1132717-002	Coliform	Storage Tank	Water Monitoring

PG&E OAKHURST SERVICE CENTER
CCR Login Linkage - 2011

FGL CODE	DATE SAMPLED	LAB ID	METHOD	DESCRIPTION	PROPERTY
STRGE TANK	04/13/2011	STK1133124-002	Coliform	Storage Tank	Water Monitoring
STRGE TANK	04/18/2011	STK1133258-003	Coliform	Storage Tank	Drinking Water Monitoring
	05/11/2011	STK1133984-003	Coliform	Storage Tank	Drinking Water Monitoring
	06/08/2011	STK1134888-003	Coliform	Storage Tank	Drinking Water Monitoring
	07/13/2011	STK1136090-003	Coliform	Storage Tank	Drinking Water Monitoring
	08/10/2011	STK1137097-003	Coliform	Storage Tank	Drinking Water Monitoring
	09/14/2011	STK1138101-003	Coliform	Storage Tank	Drinking Water Monitoring
	10/12/2011	STK1139091-003	Coliform	Storage Tank	Drinking Water Monitoring
	10/13/2011	STK1139156-003	Coliform	Storage Tank	Drinking Water Monitoring
	11/16/2011	STK1150193-003	Coliform	Storage Tank	Drinking Water Monitoring
	12/14/2011	STK1150977-003	Coliform	Storage Tank	Drinking Water Monitoring
Wash Rack	08/29/2008	VI 0841957-006	Metals, Total	Wash Rack	Bacteria Monitoring
WELL	12/16/2009	STK0951513-001	Wet Chemistry	Source Main Well	Water Quality Monitoring
	08/30/2010	STK1037633-001	Asbestos	Source Main Well	Water Quality Monitoring
	08/30/2010	STK1037633-001	Wet Chemistry	Source Main Well	Water Quality Monitoring
	01/12/2011	STK1130442-004	Coliform	Source Main Well	Drinking Water Monitoring
	02/09/2011	STK1131275-004	Coliform	Source Main Well	Drinking Water Monitoring
	03/09/2011	STK1132061-004	Coliform	Source Main Well	Drinking Water Monitoring
	04/03/2011	STK1132717-001	Coliform	Source Main Well	PG&E OAKHURST SERVICE CENTER
	04/13/2011	STK1133124-001	Coliform	Source Main Well	Water Monitoring
	04/18/2011	STK1133258-004	Coliform	Source Main Well	Drinking Water Monitoring
	05/11/2011	STK1133984-004	Coliform	Source Main Well	Drinking Water Monitoring
	06/08/2011	STK1134888-004	Coliform	Source Main Well	Drinking Water Monitoring
	07/13/2011	STK1136090-004	Coliform	Source Main Well	Drinking Water Monitoring
	08/10/2011	STK1137097-004	Coliform	Source Main Well	Drinking Water Monitoring
	09/14/2011	STK1138101-004	Coliform	Source Main Well	Drinking Water Monitoring
	10/12/2011	STK1139091-004	Coliform	Source Main Well	Drinking Water Monitoring
	10/13/2011	STK1139156-001	Coliform	Source Main Well	PG&E OAKHURST SERVICE CENTER
	11/16/2011	STK1150193-004	Coliform	Source Main Well	Drinking Water Monitoring
	12/14/2011	STK1150977-004	Coliform	Source Main Well	Drinking Water Monitoring
	12/15/2011	STK1151008-001	Metals, Total	Source Main Well	Water Quality Monitoring
	12/15/2011	STK1151008-001	Wet Chemistry	Source Main Well	Water Quality Monitoring
Well 01	04/06/2009	VI 0940674-001	EPA 507	Source Main Well - Inactive	Water Quality Monitoring
	04/06/2009	VI 0940674-001	EPA 524.2	Source Main Well - Inactive	Water Quality Monitoring
	06/01/2009	VI 0941199-001	EPA 524.2	Source Main Well - Inactive	Water Quality Monitoring
	09/14/2009	VI 0942232-001	EPA 524.2	Source Main Well	Water Quality Monitoring
	09/14/2009	VI 0942232-001	Wet Chemistry	Source Main Well	Water Quality Monitoring
Well Head	12/31/2008	VI 0843176-001	EPA 504.1	Well Head	Water Quality Monitoring
	12/31/2008	VI 0843176-001	EPA 507	Well Head	Water Quality Monitoring
	12/31/2008	VI 0843176-001	EPA 524.2	Well Head	Water Quality Monitoring
Westside of Off	08/29/2008	VI 0841957-004	Metals, Total	Mens Restroom	Bacteria Monitoring
	08/29/2008	VI 0841957-005	Metals, Total	Westside of Office	Bacteria Monitoring
Womens Restroom	08/29/2008	VI 0841957-003	Metals, Total	Womens Restroom	Bacteria Monitoring